

Standard Sizes of Processed Aggregate

Size	Percent By Weight Passing Each Laboratory Sieve														
Number	4"	3½"	3"	2½"	2"	1½"	1"	¾"	½"	3/8"	No. 4	No. 8	No. 16	No. 50	No. 100
1	100	90-100	-	25-60	-	0-15	-	0-5							
2			100	90-100	35-70	0-15	-	0-5							
24			100	90-100	-	25-60	-	0-10	0-5						
3				100	90-100	35-70	0-15	-	0-5						
357				100	95-100	-	35-70	-	10-30	-	0-5				
4					100	90-100	20-55	0-15	-	0-5	-				
467					100	95-100	-	35-70	-	10-30	0-5				
5						100	90-100	20-55	0-10	0-5	-				
56						100	90-100	40-85	10-40	0-15	0-5				
57						100	95-100	-	25-60	-	0-10	0-5			
6							100	90-100	20-55	0-15	0-5	-			
67							100	90-100	-	20-55	0-10	0-5			
68							100	90-100	-	30-65	5-25	0-10	0-5		
7								100	90-100	40-70	0-15	0-5	-		
78								100	90-100	40-75	5-25	0-10	0-5		
8									100	85-100	10-30	0-10	0-5		
89									100	90-100	20-55	5-30	0-10	0-5	
9										100	85-100	10-40	0-10	0-5	
10										100	85-100	-	-	-	10-30