



Example 4d-1: Draw the shear and moment diagrams for the following frame:

2/2



MAX. VALUES

$$\begin{aligned} M_{AB} &= 216 \text{ kft} \quad \odot B \\ M_{BC} &= 216 \text{ kft} \quad \odot B \\ M_{CD} &= 0 \end{aligned}$$